CIVIL XPERTS
ISO 9001:2008
CONSULTANTS & TESTING CENTER

174, Sri Ranga Complex
Amrutha Nagar Main Road
New Bank Colony, Konanakunte
Bangalore - 560 062.
Mobile : +91 97429 59595
Tele/Fax : 080-2632 2565
E-mail : civilexpertsltd@gmail.com
URL : www.civilexperts.in

NABL ACCREDITED AS PER ISO/IEC 17025:2005

Name of Work : **Providing and Laying HDPE water Line in Mohan Kumar Nagara Block-III in J P Park, Ward No.17**

Name of Client	:	**Executive Engineer,** Rajarajeshwari Nagara Division, BBMP, Bangalore.
Contractor/Agency	:	**Sri. Damodar & Co,** Contractor, BBMP, Bangalore.
Date of Inspection	:	20.05.2014
Status of Bill	:	1st and Final Bill
In the Presence of	:	(a) **Assistant Engineer,** Ward No.17, BBMP, Bangalore.
	:	(b) **Mr. Madhu,** Site Engineer, M/s Civil Experts Consultants & Testing Center, Bangalore.
		(c)**Sri. Damodar & Co,** Contractor, Bangalore.

PMC Compliance Report

BOQ. No	Description of the Item		Comments / observations
1	Earth Work excavation for Foundation of Buildings culverts Water Supply ,……	:	Work done up to the billed quantity and Quality is satisfactory
2	Providing and Fixing to Wall Ceilling and floor high Density …….. ….	:	Work done up to the billed quantity and Quality is satisfactory
3	Providing and fixing to wall Celling and floor high density Polyethylene pipes 6.00…….. ……..	:	Work done up to the billed quantity and Quality is satisfactory
4	Providing and fixing in Trenches galvanised /mild steel tubes……..….	:	Work done up to the billed quantity and Quality is satisfactory

Scanned by CamScanner

CIVIL XPERTS
ISO 9001:2008
CONSULTANTS & TESTING CENTER

174, Sri Ranga Complex
Amrutha Nagar Main Road
New Bank Colony, Konanakunte
Bangalore - 560 062.
Mobile : +91 97429 59595
Tele/Fax : 080-2632 2565
E-mail : civilexpertsltd@gmail.com
URL : www.civilexperts.in

NABL ACCREDITED AS PER ISO/IEC 17025:2005

5	Providing and fixing 25mm dia nipple, complete as per specifications and as directed.....	:	Work done up to the billed quantity and Quality is satisfactory
6	Providing and fixing reducer elbow 25mm to 20mm complete	:	Work done up to the billed quantity and Quality is satisfactory
7	Providing and fixing 20mm dia nipple complete as per specification	:	Work done up to the billed quantity and Quality is satisfactory
8	Providing and fixing HDPE 90*32 mm saddle with brass nuts and bolts including	:	Work done up to the billed quantity and Quality is satisfactory
9	Providing and fixing 20mm dia union, complete as per specifications.....	:	Work done up to the billed quantity and Quality is satisfactory
10	Providing and fixing 20mm dia hose coller complete as per specifications....., ...	:	Work done up to the billed quantity and Quality is satisfactory
11	Providing and fixing 20mm elbow complete as per specification.....	:	Work done up to the billed quantity and Quality is satisfactory
12	Providing and fixing 20mm to 15mm reducer elbow complete as per specification.....	:	Work done up to the billed quantity and Quality is satisfactory
13	Providing and fixing 20mm NP bib cock....	:	Work done up to the billed quantity and Quality is satisfactory
14	Refilling available Earth around pipe line....	:	Work done up to the billed quantity and Quality is satisfactory
15	Providing, laying, spreading and compacting graded stones aggregate to wet mix	:	Work done up to the billed quantity and Quality is satisfactory

Scanned by CamScanner

CIVIL XPERTS
ISO 9001:2008
CONSULTANTS & TESTING CENTER

174, Sri Ranga Complex
Amrutha Nagar Main Road
New Bank Colony, Konanakunte
Bangalore - 560 062.
Mobile : +91 97429 59595
Tele/Fax : 080-2632 2565
E-mail : civilexpertsltd@gmail.com
URL : www.civilexperts.in

NABL ACCREDITED AS PER ISO/IEC 17025:2005

16	Providing and applying primer coat with S.S. bitumen emulsion on prepared surface….	:	Work done up to the billed quantity and Quality is satisfactory
17	Providing and laying bituminous macadam….	:	Work done up to the billed quantity and Quality is satisfactory
18	Providing and applying tack coat on the prepared black topped surface…	:	Work done up to the billed quantity and Quality is satisfactory
19	Providing and laying semi dense bituminous concrete….	:	Work done up to the billed quantity and Quality is satisfactory
20	Providing and laying in position plain cement concrete of mix M10….	:	Work done up to the billed quantity and Quality is satisfactory
21	Providing and laying in position plain cement concrete of mix M20….	:	Work done up to the billed quantity and Quality is satisfactory
22	Conveying the excavated earth silt debris….	:	Work done up to the billed quantity and Quality is satisfactory

Authorised Signatory
Civil Experts Consultants
174, Amruthanagara Main Road
New Bank Colony, Konanakunte
Bangalore-560 062

Scanned by CamScanner